ABI MANUFACTURING INT Ltd.

38/66 Moo4 Tambon Lamlukka, Ampher Lamlukka, Pathumthani 12150 Tel.662-1506711-2 Fax 662-987-1190 email abimfgint@gmail.com

www.allurametals.com

MATERIAL SAFETY DATA SHEET

PRODUCT:	#670 YELLOW ALLOY			
INGREDIENTS:	PRECENT	CAS NO.	PEL	TLV
ZINC COPPER SILVER SILICON BORON	0.00- 3.00 10.00-50.00 40.00-70.00 0.00- 3.00 0.00- 1.00	7440-66-6 7440-50-8 7440-22-4 7440-21-3 7440-42-8	5mg/m .10mg/m 0.2mg/m .01mg/m 10mg/m3 10mg/m3 1mg/m	5mg/m as zn0 0.2mg/m .01mg/m 10mg/m3 10mg/m3 1mg/m3

HAZARDOUS INGREDIENTS: N/A

PHYSICAL DATA: MELTING POINT: 2000 F BOILING POINT: 4650 F DENSITY/SPECIFIC GRAVITY: N/A PERCENT VOLATILE BY VOLUME: N/A EVAPORATION RATE: N/A/ APPERANCE: SOFT, DUCTILE, MALLEABLE, LUSTROUS METAL

FIRE AND EXPLOSIVE HAZARD DATA: N/A/

REACTIVITY DATA:

STABILITY: STABLE CONDITION TO AVOID: OVER HEATING HAZADROUS DECOMPOSITION: NONE HAZARDOUS POLYMERIZARTION: N/A NOTE: MAY REACT WITH ACIDS

PHYSIOLOGIAL EFFECTS:

CHRONIC OCCUPATIONAL EXPOSURE COULD RESULT IN ARGYRIA, PERMAMENT PIGMENTATION (GRAY TO PURPLE) OF THE SKIN AND EYES. LOCALIZATION ARGYRIA MAY OCCURE O THE SKIN FOR HANDLING FROM EMBEDDED PARTICLES OR FROM SKIN ABSORPTION. INHALATION MAY LOCALIZE THE ARGYRIA IN THE RESPRIATORY TRACT WITH CHRONIC BRONCHITIS AS THE ONLY SYMPTIONS. OVERHEATING COULD RESULT IN ZINC OXIDE SUCH AS METAL FUME FEVER, GASROINTISTIAL DISORDERS AND HEPTIC DYSFUNCTION.

SPILL OR LEAK PROCEDURES:

SCOOP UP AND PLACE IN SUITABLE CONTAINER

SPECIAL PROTECTION INFORMATION:

RESPIRATORY PROTECTION: APPROVED FACE MASK VENTILATION OF ANY NORMAL CLEAN AIR PROCEDURE IS APPICABLE PROTECTIVE GLOVES WHEN CASTING EYE PROTECTION WHEN CASTING OR GRINDING